

RECEIVING INSPECTION REPORT
HYCON MFG. COMPANY

No. 128105

RECEIVED FROM

Approved For Release 2001/03/04 : CIA-RDP81B00879R00050008012-9

DATE REC'D 1-16-57
P.O. NO. 10075
VENDOR PACKING SLIP NO. 10520ACCT. OR
R. W. O. NO.

S. C. NC.

CHARGE TO

CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.	QUANTITY	REMARKS
QUANTITY RECEIVED	DRAWING NO. AND DESCRIPTION							ACCEPTED	REJECTED
10	730163-50	PLTD. ALUM. ANGLE, CANTON	100000	100	0	0	0	100	

RECEIVED BY

INSPECTED BY

DATE

REJECTS RETURNED
ON SHIP. MEMO NO.

1/17/57

No. 128142

RECEIVING INSPECTION REPORT
HYCON MFG. COMPANY
2961 E. COLORADO ST., PASADENA 8, CALIF.

DATE REC'D 1-17-57

P.O. NO. 10077

VENDOR PACKING SLIP NO. 34332

RECEIVED FROM

CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.	QUANTITY	REMARKS
QUANTITY RECEIVED	DRAWING NO. AND DESCRIPTION							ACCEPTED	REJECTED
11	730163-50	BOLT CAD. PLATE STEEL	100000	0	0	00	00	11	

INSPECTED BY

DATE

REJECTS RETURNED
ON SHIP. MEMO NO.

Approved For Release 2001/03/04 : CIA-RDP81B00879R00050008012-9

RECEIVED BY